

# CERTIFIED CORNER RECORDATION

Corner east one-sixteenth corner common to sections 30 and 31 T. 26 NORTH R. 5 WEST P.M.M. TETON County

RECORD: Nothing

FOUND: Nothing


**SET:**

A 5/8" diameter Rebar 24" in length, with a 2.5" Aluminum Cap at midpoint between the quarter corner and section corner flush with the ground and is inscribed as shown:

Corner is next to a down guy on the east side of a power pole north of an east-west fence.



SEE CORRECTIVE SURVEY OF TOWNSHIP 26 NORTH RANGE 5 WEST PREPARED FOR THE PUBLIC



SKETCH OF CORNER

**CERTIFICATION**

I, MARK THEODOR LARSON, PLS

certify the information shown herein is true and correct, and that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

*Mark Theodor Larson*  
Signature of Surveyor & Seal

Date: DECEMBER 11, 2019 Reg. No. Montana PLS #19235

Employer: MORRIS LAND SURVEYS, P.L.L.C.

Office of Clerk and Recorder, County of TETON . This 'corner

record' was filed for rec **449328** Fee: **\$0.00** Bk: **Pg:**

TETON COUNTY, MT Filed 12/12/2019 At 2:44 PM

was noted on the cross-PAULA JACONETTY, Clk & Rcdr By *Paula Jaco*


Return To: OFFICE

book No. \_\_\_\_\_

Cross Index No. V4 T. 26N R. 5W P.M.M.

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

Sec. 31



● corner this sheet

**Morris Land Surveys, P.L.L.C.**

**P.O. Box 513, 19 3rd St. NE, Choteau, MT 59422 (406) 466-3550**